SAF

Update for SAF TIRE PILOT I.Q. regarding ECE R156

Following the update on **1 April 2026**, the SAF TIRE PILOT I.Q. system no longer applies to ECE R156.
The update includes new firmware for the control box and the associated desktop app, which is required for initial commissioning.

With these changes, no software updates in accordance with ECE R156 are possible in the field.

The SAF TIRE PILOT I.Q. is therefore outside the scope of ECE R156.
The changes have no impact on the existing type-approval of the SAF TIRE PILOT I.Q. system in accordance with ECE R141. **The test reports remain valid.**

Updated Part Numbers

Item	Part Number	Firmware Version
Basic Kit Haldex	03 001 0271 02	
Basic Kit WABCO	03 001 0301 02	3.1.01
Basic Kit Knorr	03 001 0302 02	

To commission control boxes with firmware version 3.1.01, the desktop app version 3.2.2 is required. This is now available on the SAF-HOLLAND I.Q. Portal.

A detailed description of the changes to the functionality of the system and the desktop app can be found in the following document:

https://safholland.com/de/en/service/download-center/document/resource/environment/project1_p/documents/documentationP/2026/2026_03/Update%2520Tire%2520Pilot%2520IQ_EN.pdf

SAFholland
Group