

## Change in control box of the SAF TIRE PILOT tyre inflation system

As part of ongoing product improvement, the control box of the SAF Tire Pilot tyre inflation system is being replaced by a revised model.

In order to simplify the assembly procedure still further during installation, the new control box generates the energy required for the warning lamp itself. It no longer has to be connected to the trailer wiring system. The warning light is now connected directly to the control box.

The basic function, the dimensions and the connecting dimensions of the SAF Tire Pilot are not affected.

The new control box can be used to replace the old control box. The wiring of the warning light must be changed in accordance with the enclosed wiring diagram (operating manual).



The switchover is planned for October 2016. From this time, the KIT will be delivered only with the updated control box.

	Old number	New number
Trailer Basis Kit	03 001 0184 00	03 001 0184 01
Operating manual	XL-TP11697UM-DE-DE 02.2012	XL-TP11697UM-DE-DE Rev B 03.2016