

HOLLAND Fifth Wheels

Retirement of FW16 Low Lube Fifth Wheel Assemblies

Attention

This product retirement notice applies to all HOLLAND FW16 Low Lube fifth wheels.

Effective April 1, 2019, SAF-HOLLAND will retire the FW16 Low Lube fifth wheel assemblies sold to all customers.

Service parts and replacement top plate assemblies will be available through the SAF-HOLLAND aftermarket.

Aftermarket replacement rebuild kits, including lube plate replacement kits, will be available for an extended period. Replacement top plates will be available for a limited time.

Customers seeking a Low Lube fifth wheel assembly should consider the FW33 Low Lube fifth wheel as an alternative.

If you have any questions or require additional product assistance, please contact your account manager or customer service representative.

Discontinued Effective January 1, 2019 FW16 Low Lube Fifth Wheel



Alternative Model Offering FW33 Low Lube Fifth Wheel

