

Service Kit 950 364 506

1


364 208 001




059 5123 09



042 5857 09



2




3

4


364 208 001

059 5123 09




5


042 5857 09




6




7



8



9








ABS/EBS System 80/100 Tooth Straight Sensor

Sensor Replacement
Auswechseln des Sensors
Remplacement capteur
Recambio del sensor
Wymiana czujnika
Cambio del sensore



www.haldex.com



www.haldex.com