

HOLLAND Coupling

Product Change Notification for HOLLAND CP-740 Coupler

Effective Date: December 1, 2023

Equipment Option Change:

Obsolescence of model CP-740

Attention:

The CP-740 is being discontinued due to low sales. There is no direct replacement for this coupler. Please review the Coupler Selection Guide XL-PH13975G-en-US for another coupling product that fits your application.

If you have any questions or require additional product assistance, please contact your account manager or customer service representative at 800.876.3929.

Service parts will be available through the SAF-HOLLAND Aftermarket for a seven year period.

CP-740

