



## Important Info – August 2021

---

### HOLLAND Fifth Wheels

#### Market Notification for Upcoming Fifth Wheel Product Changes

##### FW2000 and FW3500 Rebuild Kits

The rebuild kits containing the lock set for the XA-2009 and XA-3501 top plates are being discontinued. Due to a supply chain disruption, the locks will no longer be available once inventory has been consumed. Supply will be limited to the existing inventory of kits. Please check with your account or service representative for availability. There is no direct replacement for these kits.

Kits with very limited availability include the following:

- RK-1707-M
- RK-05329
- RK-06122
- RK-63501
- RK-63503
- RK-63503-A
- RK-63509

The following kits will no longer be available when inventory has been consumed:

- RK-0093-1
- RK-03618
- RK-05328
- RK-05466
- RK-06123
- RK-06146
- RK-06147
- RK-1117-1
- RK-1117-1-L
- RK-1117-6-L
- RK-1118-2-L
- RK-1707-5
- RK-1707-6
- RK-1707-6-P
- RK-2009-S05418-1
- RK-62000
- RK-62000-1
- RK-62001
- RK-62001-1
- RK-62002
- RK-62002-1
- RK-62011
- RK-62011-S07645
- RK-62012
- RK-62013
- RK-62014
- RK-62014-1
- RK-62014-2
- RK-62014-3
- RK-63500
- RK-63500-D
- RK-63503-82
- RK-63505-1
- RK-63506
- RK-63506-1
- RK-63508
- RK-63510
- RK-63511
- RK-S03013
- RK-S03014
- RK-S04533
- RK-S04534
- RK-S06593-L
- RK-S07445
- RK-S08693
- RK-S08694