



## Important Info – August 2021

---

### HOLLAND® Fifth Wheels

#### Market Notification for Upcoming Fifth Wheel Product Changes

##### **FW31 NoLube Product Retirement Notification**

The Holland FW31 NoLube Fifth Wheel will no longer be available starting January 1, 2022. The alternate product is the FW33 LowLube Fifth Wheel. Aftermarket service kits will continue to be available for FW31 customers, but FW31 top plates will not be available as replacements. Customers can substitute the FW33 as an alternate product. OEM and Aftermarket orders placed prior to December 31, 2021 will be fulfilled. Please work with your account representative for alternate production part numbers.

##### **Corrugated Mounting Plates**

###### **Option Code 01, 04, 08 and 1D Product Retirement Notification**

The standard offering option codes related to the corrugated mounting plate will no longer be available starting January 1st, 2022. Customers requiring the mounting plate will be able to purchase the XA-0686 plate separately. Specials, those part numbers with the –S designation after the top plate model, will not be affected by this change including FW35-S10540 Series specials. OEM and Aftermarket orders placed prior to December 31, 2021 will be fulfilled.

##### **Manual Secondary Locks**

###### **Option Code 02, 04, 27, 34, 45, 48, 60, 97, 98, 0F, 0R, 1A, E2, 1E, 1H and 1N Product Retirement Notification**

The standard offering option codes related to the FW35 series manual secondary lock will no longer be available starting January 1, 2022. The FW35 and FW33 Fifth Wheel models come standard with an automatic secondary lock that doesn't require human interaction to activate. Customers requiring the manual secondary lock are encouraged to work with their account manager and applications engineering for alternate options. Service kits related to the manual secondary lock will continue to be available. OEM and Aftermarket orders placed prior to December 31, 2021 will be fulfilled. Military specials will not be affected by this change.

##### **Air Release Control Kits**

###### **Option Code 86, 0A, 1E, E6, 1G and 1Y Product Retirement Notification**

The standard offering option codes related to the air release control kit will no longer be available starting January 1, 2022. Customers looking to retrofit a tractor with air release can purchase the option code for factory installed air release (Option 80) and the RK-06559 air control kit. The RK-06559 air controls kit is only required to install an air release fifth wheel top plate on a tractor built without an air release fifth wheel top plate. Customers with existing air release top plates should purchase the 80 option code or one of the combination codes for air release combined with another standard option for a direct replacement. Contact your account manager or customer service representative for replacement part numbers. Aftermarket orders placed prior to December 31, 2021 will be fulfilled.

---

Tel 800.876.3929 · info@safholland.us · 2021-08-23 · XL-FW20137WI-en-US Rev A