## Important Information P89 Air Disc Brake

## ABS Sensor Block For P89 Integral and P89 Plus

Beginning with shipments in October 2017, SAF-HOLLAND<sup>®</sup> implemented a design change to the ABS sensor mounting block for P89 INTEGRAL<sup>®</sup> and P89 Plus air disc brake axles (except self-steering axles). (The new sensor block will have two (2) mounting positions to accommodate different rotor designs and ABS tone positions.)

Axles equipped with SAF-HOLLAND'S P89 INTEGRAL and P89 Plus air disc brake systems will continue to utilize the angled ABS mounting hole.




## February, 2018

**NOTE:** For P89 Integral and P89 Plus a reverse sensor must use the angled hole. If reverse sensor and ABS sensors are required on the same axle, an additional mounting block is required. Please refer to reverse sensor manufacturer's installation instructions.

This product change does not affect the functionality of the disc brake system. If you have any questions or require additional product assistance, please contact your SAF-HOLLAND sales or service representative at (888) 396-6501 or visit our website at www.safholland.us.

## Figure 1







From fifth wheel rebuild kits to suspension bushing repair kits, SAF-HOLLAND Original Parts are the same quality components used in the original component assembly.

SAF-HOLLAND Original Parts are tested and designed to provide maximum performance and durability. Will-fits, look-alikes or, worse yet, counterfeit parts will only limit the performance potential and could possibly void SAF-HOLLAND's warranty. Always be sure to spec SAF-HOLLAND Original Parts when servicing your

SAF-HOLLAND product.

SAF-HOLLAND USA • 888.396.6501 • Fax 800.356.3929 www.safholland.us

SAF-HOLLAND CANADA • 519.537.3494 • Fax 800.565.7753 WESTERN CANADA • 604.574.7491 • Fax 604.574.0244 www.safholland.ca

SAF-HOLLAND MEXICO • 52.55.5362.8743 • Fax 52.55.5362.8743 www.safholland.com.mx

info@safholland.com

