



**VCA Headquarters**  
1 The Eastgate Office Centre  
Eastgate Road  
Bristol, BS5 6XX  
United Kingdom

Switchboard: +44 (0) 117 951 5151  
Main Fax: +44 (0) 117 952 4103  
Email: [enquiries@vca.gov.uk](mailto:enquiries@vca.gov.uk)  
Web: [www.vca.gov.uk](http://www.vca.gov.uk)

THE UNITED KINGDOM VEHICLE APPROVAL AUTHORITY

Rev 1/03

---

COMMUNICATION CONCERNING THE GRANTING OF EEC TYPE APPROVAL AS A  
COMPONENT OF MECHANICAL COUPLING DEVICES FOR MOTOR VEHICLES AND THEIR  
TRAILERS PURSUANT TO DIRECTIVE 94/20/EC OF 30 MAY 1994 (STU)

---

Type Approval No<sup>(1)</sup>: e11\*94/20\*7609\*00

Reason for Extension: Not applicable

SECTION I


- 0.1 Make (trade name of manufacturer): +GF+ or SAF or Holland or SAF-Holland
- 0.2 Type and general commercial description(s): SK-V36 / non standard mounting plate
- 0.3 Means of identification of type if marked on the component<sup>(2)</sup>: Make (trade name), type and class
- 0.3.1 Location of that marking: Manufacturers plate fixed by rivets, adhesive or embossed at the side of the coupler plate
- 0.4 Category of vehicle <sup>(2)</sup>: N1, N2, N3
- 0.5 Name and address of manufacturer:  
SAF-Holland Verkehrstechnik GmbH  
Julius Bühler Strasse  
78201 Singen  
Germany



0.8 Name(s) and address(es) of assembly plants:

SAF-Holland Verkehrstechnik GmbH  
Julius Bühler Strasse  
78201 Singen  
Germany

## SECTION II

1. Additional information (where applicable): See Appendix I
2. Technical service responsible for carrying out the tests: TÜV SÜD Automotive GmbH
3. Date of test report: 03 June 2009
4. Number of test report: 09-00204-CX-GBM
5. Remarks (if any): See Appendix I
6. Place: BRISTOL
7. Date: 16 JUNE 2009
8. Signature:  A. W. STENNING  
Head of Technical and Quality Group
9. The index to the information package lodged with the competent authority that has granted type approval, which may be obtained on request, is attached.
  - (1) The EEC type approval number appearing on this document shall consist of all sections outlined in Annex VII to Directive 70/156/EEC as last amended by Directive 92/53/EEC. The component itself shall be marked as prescribed in the relevant separate Directive.
  - (2) If the means of identification of type contains characters not relevant to describe the component types covered by this type approval certificate such characters shall be represented in the documentation by the symbol '?' (e.g. ABC??123??).

**APPENDIX I**

to EEC Type Approval Certificate No: e11\*94/20\*7609\*00

concerning the component type-approval of mechanical coupling devices  
with regard to Directive 94/20/EC

1. ADDITIONAL INFORMATION
- 1.2 Class and type of the coupling device(s) <sup>(1)</sup>: J, SK-V36
- 1.3 Use of towing brackets or mounting plates, attachment instructions of the coupling type:  
See Manufacturer's Documents
- 1.4 EEC vehicle type approval is granted to the following type(s) of coupling device and class(es): See item 1.2
- 1.6 Maximum V-value: Not applicable
- 1.6.1 Maximum mass of the combination: Not applicable
- 1.7 Maximum vertical load U of the vehicle type fitted with the coupling device: 36 tonnes
- 1.8 Maximum D-value: 260 kN
- 1.9 Maximum mass of the towing vehicle (T) or maximum mass of the vehicle combination (if T is less than 32 tonnes): Not applicable
5. Remarks <sup>(3)</sup>: None

<sup>(1)</sup> Including information as to whether fifth wheel couplings are unsuitable for positive steering.

<sup>(2)</sup> If applicable

<sup>(3)</sup> Including information as to whether fifth wheel couplings are unsuitable for positive steering.



**VCA Headquarters**  
1 The Eastgate Office Centre  
Eastgate Road  
Bristol, BS5 6XX  
United Kingdom

Switchboard: +44 (0) 117 951 5151  
Main Fax: +44 (0) 117 952 4103  
Email: [enquiries@vca.gov.uk](mailto:enquiries@vca.gov.uk)  
Web: [www.vca.gov.uk](http://www.vca.gov.uk)

APPROVAL NUMBER: e11\*94/20\*7609\*00

## INFORMATION PACKAGE CONTENTS

### INDEX

**REVISION NUMBER: Not applicable**

Total number of sheets:	44 (Forty-four)
Number of separate drawings:	0 (Nil)
Number of separate photographs:	0 (Nil)

Reasons for Revision: Not applicable

Revision date  
&  
Office stamp

