



## Important Info – December 2019

### HOLLAND Bumper Tubes

#### Retirement Notice for HOLLAND Trailer Bumper Tube Products

##### Attention

SAF-HOLLAND® is announcing the discontinuation of HOLLAND trailer bumper tube line for both OEM and Aftermarket customers. This includes all TB-0273 and TB-0278 part numbers and supporting decal (XB-DCL-031-81).

##### Effective


May 31<sup>st</sup>, 2020 - No new orders will be accepted.

June 30<sup>th</sup>, 2020 - SAF-HOLLAND will cease production.

The SAF-HOLLAND sales team is communicating with customers who currently specify all TB-0273 and TB-0278 trailer bumper tubes concerning the retirement of the products.

If you have any questions or require additional product assistance, please contact your account manager or customer service representative.

TB-0273 and TB-0278 Trailer Bumper Tubes



Tel 888.396.6501 · info@safholland.us · 2019-12-16 · XL-RF20005WI-en-US Rev B