Important Info – October 2018



HOLLAND Fifth Wheels

Retirement of FW0001, FW0002, FW1900, FW6000 Fifth Wheels, and KP-6500 Kingpin

Attention


Effective January 1, 2019, SAF-HOLLAND will retire the FW0001, FW0002, FW190, FW6000 fifth wheel assemblies, and KP-6500 kingpin.

This product retirement notice applies to the following HOLLAND fifth wheels:

- FW0001
- FW0002
- FW1900
- FW6000
- KP-6500

Orders for the products will be accepted until January 1, 2019. Service parts, replacement kits, and replacement top plate assemblies will be available through the SAF-HOLLAND aftermarket for a limited time.

If you have any questions or require additional product assistance, please contact your account manager or customer service representative.



Tel 888.396.6501 · info@safholland.us · 2018-10-17 · XL-FW20163WI-en-US Rev A

