



## Important Info – April 2020

### HOLLAND Coupling Products

#### Retirement Notice for HOLLAND Ground Support Equipment Coupling Models

- CP-400-GSE Models
- EH-3050 Models
- EH-HD Models
- DB-020FK1 Models
- TB-2000 Models
- XA-T-150-AF Models
- DB-010EJ1 Models

#### Attention

SAF-HOLLAND® is announcing the discontinuation of all HOLLAND TB-2000, CP-400-GSE, XA-T-150-AF, EH-HD and EH-3050 as well as the following DB-010EJ1 and DB-010FK1 ground support equipment coupling models for both OEM and Aftermarket customers.

#### Effective

Due to the Covid-19 pandemic, we have extended availability of our GSE production Line to ensure a smooth transition.

June 30<sup>th</sup>, 2020 - No new orders will be accepted.

July 31<sup>st</sup>, 2020 - SAF-HOLLAND will cease production.

Service parts will be available through the SAF-HOLLAND Aftermarket for a limited time.

The SAF-HOLLAND sales team is communicating with customers who currently specify the TB-2000, CP-400-GSE, XA-T-150-AF, EH-HD and EH-3050 as well as the following DB-010EJ1 and DB-010FK1 models concerning the retirement of the products.

If you have any questions or require additional product assistance, please contact your account manager or customer service representative.

CP-400-GSE Models



XA-T-150-AF Models



TB-2000 Models



EH-3050 Models



EH-HD Models



DB-010EJ1 Models



DB-020FK1 Models

